Ref #	Hits	Search Query	DBs	Default Operator	Piurals	Time Stamp
L2	3	(Step\$5 adj motor).clm. and voltage.clm. and current.clm. and square.clm.	US-PGPUB	OR	ON	2006/01/04 12:18
L3	96	(Step\$5 adj motor).clm. and voltage.clm. and current.clm.	US-PGPUB	OR	ON	2006/01/04 12:16
L4	3	(Step\$5 adj motor).clm. and voltage.clm. and current.clm. and (sine or cosine).clm.	US-PGPUB	OR	ON	2006/01/04 12:18
L5	54	(motor).clm. and voltage.clm. and current.clm. and (sine or cosine). clm.	US-PGPUB	OR	ON	2006/01/04 12:18
L6	106	motor.clm. and voltage.clm. and current.clm. and square.clm.	US-PGPUB	OR	ON	2006/01/04 12:18
L7	6	(motor).clm. and voltage.clm. and current.clm. and (sine or cosine). clm. and square.clm.	US-PGPUB	OR	ON	2006/01/04 12:18